





				<b>Preliminary Present Value End of Life (PVEOL) Analysis</b>			
<b>Network area:</b>	<b>Highway:</b>	<b>RP:</b>	<b>BSN:</b>	<b>Structure name:</b>	<b>Owner:</b>	Far North District Council	
Northland	Puhata Rd	2162		<b>Puhata Road Bridge No. D50</b>	<b>RCA:</b>	Far North District Council	
<b>General Structure Data</b>				<b>PVEOL Questions:</b>	<b>Yes/No</b>	<b>Brief explanation of restrictions</b>	
<b>Year constructed:</b>	1950			Is the bridge over 80 year old	No	The bridge is in an extremely poor condition and posted accordingly at 30% of class one, 7000kg axle limits and speed restrictions of 10km/hr.	
<b>One Network Road Classification (ONRC):</b>	Access (low volume)			Is there significant maintenance required in the next 3 years	Yes		
<b>Vehicles per day:</b>	<50			Is the bridge inspected in accordance with NZTA-S6	Yes		
<b>% heavy vehicles:</b>	10.0%			Is the bridge on special inspections	Yes		
<b>Number of Spans</b>	1			Has a live load assessment been carried out based on the known condition	Yes		
<b>Total Length of Bridge</b>	9m			Are there any brittle and/or vulnerable details on the bridge	Yes		
<b>Road width between Kerbs/rails</b>	2.8m			Are there live load or speed restrictions across the bridge	Yes		
<b>Structure description</b>				<b>Photo from Road Level</b>		<b>Photo of Elevation</b>	
<p>The road bridge is a single lane, single span structure and is approximately 9 m long x 2.8 m wide between kerbs. It has a steel beam superstructure and timber decking. There are no abutments however, with the beams sitting on timber planks which sit on the ground. The bridge was constructed 1950.</p> <p>The structure was not considered a council asset for a significant portion of its life, and hence, has never been maintained.</p>							
<b>Current Condition</b>	<b>Briefly explain the current defects</b>				<b>Representative photo of condition</b>		
<b>Parapets / Barriers / Surfacing</b>	The deck is in a heavily deteriorated state. Timber elements are heavily worn, and spongy when wet. Railings are only present on one side. These are in a rotten state.						
	<b>Maintenance Interventions Required</b>		<b>Year</b>	<b>Cost (\$k)</b>			
	1.) Install new handrails		2021	\$15			
	2.) Replace severely worn portions of deck		2021	\$15			
	3.) Replace severely worn portions of deck		2026	\$15			
4.)							
<b>Current Condition</b>	<b>Briefly explain the current defects</b>				<b>Representative photo of condition</b>		
<b>Superstructure</b>	The steel beams have significant corrosion and section loss across most of the beams. Due to the ends of the beams being covered in layers of mud for a significant period, the beam ends are severely corroded at bearing positions.						
	<b>Maintenance Interventions Required</b>		<b>Year</b>	<b>Cost (\$k)</b>			
	1.) Repair/strengthen existing beams		2021	\$30			
	2.) Replace superstructure		2031	\$125			
	3.)						
4.)							
<b>Current Condition</b>	<b>Briefly explain the current defects</b>				<b>Representative photo of condition</b>		
<b>Substructure</b>	As noted in the structure description, on inspection, no abutments were identified. The structure is founded on wooden planks in-ground. The adjacent picture shows the end of one of the beams when exposed from behind. End fixity is non-existent.						
	<b>Maintenance Interventions Required</b>		<b>Year</b>	<b>Cost (\$k)</b>			
	1.) Construct new piled abutments		2021	\$125			
	2.)						
	3.)						
4.)							

				<b>Preliminary Present Value End of Life (PVEOL) Analysis</b>			
Network area:	Highway:	RP:	BSN:	Structure name:	Owner:	Far North District Council	
Northland	Puhata Rd	2162		Puhata Road Bridge No. D50	RCA:	Far North District Council	

Other general photos to represent current condition



Hypothetical "like for like" bridge Replacement		Brief discussion
Total Length of Bridge	9m	Costs include for establishment, traffic management and nominal approach works. Costs do not include for consultancy fees, resource consent fees or geotechnical investigation fees.  An additional \$25,000 has been added as an overhead power line will be required to be moved.
Road width between Kerbs/rails	4m	
NZTA replacement rate (m2)	\$6,600	
Replacement cost	\$262,600	

#### Maintenance Scenarios

#### Scenario 1 - Minimal / Routine Maintenance and look to replace the bridge as early as possible (1-3 years)

Component	Maintenance Interventions Required	Year	Cost (\$k)	NPV (\$k) 4% discount
All	Replace bridge	2021	\$262	\$252
		<b>Totals</b>	<b>\$262</b>	<b>\$252</b>

#### Scenario 2 - Maintain the bridge in the medium term (3-10 years) followed by bridge replacement

Component	Maintenance Interventions Required	Year	Cost (\$k)	NPV (\$k) 4% discount
Handrails	Install new handrails	2021	\$15	\$14
Deck	Replace severely worn portions of deck	2021	\$15	\$14
Substructure	Construct new piled abutments (move power line at the same time)	2021	\$150	\$144
Superstructure	Repair/strengthen existing beams	2021	\$30	\$29
Deck	Replace severely worn portions of deck	2026	\$15	\$12
All	Replace bridge superstructure	2031	\$125	\$81
		<b>Totals</b>	<b>\$350</b>	<b>\$295</b>


#### Proposed Strategy

Having considered the condition of the bridge, there is potential that significant, potentially catastrophic, failure may occur within 1 to 3 years if maintenance actions or replacement are not undertaken. The PVEOL analysis over 10 years of asset life gives a 15% (\$43K) saving which shows that the bridge is at the end of its economic life, and therefore the preferable option is to replace the structure immediately. Due to the deterioration of the structure, the bridge will require replacement in the short to medium term, irrespective of the maintenance works level chosen. At 71 years old, and with little to no maintenance during its lifetime, the structure is also effectively at the end of its useful life.

#### Document preparation

Prepared by:	Tess Fulton	Title:	Intermediate Engineer - Civil	Date:	29/09/2021
Approved by:	Dewi Todd-Jones	Title:	Work Group Manager - Bridges, Civil & Structures	Date:	29/09/2021

#### Document review - Waka Kotahi response

Reviewed by:	Liam Coleman 	Title:	Team Lead Structural Performance	Date:	30/09/2021
--------------	--	--------	----------------------------------	-------	------------

Outcome:	Comments:
<b>APPROVED</b>	\$6600/m2 replacement value needs to be used but it wont change the decision in this case.