

Road No.	Bridge No.	FNDC Area	Roadway	Bridge Name	Span Arrangement	Culvert sizz span x v	Culvert Soffit Length	Culvert Invert Length	Description	Rough Order Cost Estimate	Aggregate Cost per year
2021-22											
2598	D41	North	Kaitaia-Awaroa Road	Kaitaia-Awaroa Road Culvert D41	1/2.0				Replacement of poor condition culvert	\$275,000	
2184	D50	North	Puhata Road	Puhata Road Bridge D50	1/8.2				Replacement of poor condition bridge	\$275,000	
1815	M35	South	Kahikatoa Road	Kahikatoa Road Culvert M35	1/1.5	1.2 x 1.5	4.0	6.0	Replacement of poor condition culvert	\$175,000	
2159	P17	South	Picadilly Road	Picadilly Road Culvert P17	1/2.1				Distortion noted in culvert. Investigation and potential design required.	\$25,000	
2585	B15	North	Wireless Road	Wireless Road Culvert B15	2/1.9				Distortion noted in culvert. Investigation and potential design required.	\$25,000	
											\$775,000
2022-23											
1601	C13	North	Churtons Road	Churtons Road Bridge C13	3/7.5/7.5/7.5				Replacement of poor condition bridge	\$700,000	
2210	B13	North	Quarry Road (Awanui)	Quarry Road (Awanui) Culvert B13	1/2.1	2.1 x 1.35	15.0	19.0	Replacement of poor condition culvert	\$275,000	
2557	UN28	North	Whangaroa Road	Whangaroa Road Culvert UN28	1/1.8	1.8 x 1.8	11.5	16.5	Replacement of poor condition culvert	\$275,000	
											\$1,250,000
2023-24											
3085	A39	North	Waharua Road	Waharua Road Culvert A39	1/2.5	2.5 x 2.1	9.0	9.0	Replacement of poor condition culvert	\$300,000	
2535	J18	South	Wekaweka Road	Wekaweka Road Culvert J18	1/3.0	3.0 x 1.8	15.0	17.0	Replacement of poor condition culvert	\$275,000	
2543	G28	North	West Coast Road (Kohukohu)	West Coast Road (Kohukohu) Culvert G28	1/4.5	4.5 x 2.6	12.0	19	Replacement of poor condition culvert	\$300,000	
											\$875,000
2024-25											
2159	P17	South	Picadilly Road	Picadilly Road Culvert P17	1/2.1				Replace poor condition culvert in time.	\$275,000	\$2,900,000
2585	B15	North	Wireless Road	Wireless Road Culvert B15	2/1.9				Investigation required. Otherwise replace poor condition culvert in time.	\$330,000	
2219	L08	South	Rakauwahia Road	Rakauwahia Road Culvert L08	1/4.5	4.5 x 3.1	13	20	Investigation required. Otherwise replace poor condition culvert in time.	\$330,000	
2284	X11	South	Russell Whakapara	Russell Whakapara Bridge X11	1/6.5				Replacement of poor condition bridge	\$440,000	
2177	D35	North	Powells Road (Diggers Valley)	Powells Road (Diggers Valley) Culvert D35	1/1.8	1.8 m	7.3	7.3	Install another barrel? Check Consent has been obtained and hydraulic capacity is adequate (unlikely).	\$220,000	
											\$1,375,000
2025-26											
2357	F15	North	Taemaro Road	Taemaro Road Culvert F15	1/3.0	2.75	15.0	15.0	Replacement of poor condition culvert	\$275,000	
1968	C03	North	Matai Bay Road	Matai Bay Road Bridge C03	2/9.2/9.2				Replacement of poor condition bridge	\$1,100,000	
											\$1,100,000
2026-27											
2598	D42	North	Kaitaia-Awaroa Road	Kaitaia-Awaroa Road Bridge D42	4/9/9/9/9				Replacement of poor condition bridge	\$2,000,000	
											\$2,000,000
2027-28											
1891	M33	South	Lake Road	Lake Road (Okaihau) Culvert M33	2/2.45	2.45 x 2.0	30	35	Replacement of poor condition culvert	\$375,000	
2543	G27	North	West Coast Road	West Coast Road Culvert G27	1/2.0				Replacement of poor condition culvert	\$275,000	
2223	G21	North	Rangi Point Road	Rangi Point Road Culvert G21	2/3.05				Replacement of poor condition culvert	\$375,000	
2108	G20	South	Otengi Road	Otengi Road Culvert G20	1/3.0				Replacement of poor condition culvert	\$275,000	
											\$1,300,000
2028-29											
2598	D47	North	Kaitaia-Awaroa Road	Kaitaia-Awaroa Road Bridge D47	3/11/11/11				Replacement of poor conditition bridge	\$2,000,000	
											\$2,000,000
2029-30											
1867	H32	North	Kohukohu Road	Kohukohu Road Culvert H32	1/7.0				Replacement of poor condition culvert	\$550,000	
1844	E94	North	Kenana Road	Kenana Road Culvert E94	1/3.0				Replacement of culvert	\$375,000	
											\$925,000
2030+											
2600	P49	South	Waimatenui-Mataraua Road	Waimatenui-Mataraua Road Culvert P49	1/3.0				Replacement of poor condition culvert	\$275,000	
1785	M36	South	Horeke Road	Horeke Road Culvert M36	1/2.2				Replacement of poor condition culvert	\$275,000	
2454	UN23	North	Totara North Road	Totara North Road Culvert UN23	1/1.9	1.9 X 1.9	8.4	12.4	Getting repaired in short term. Replacement of poor condition culvert	\$275,000	