



Photo 4: View of the foundation at the southwestern end side of the house. Foundations are getting undermined by the soil fretting – Close Out



Photo 5: Close-out of the erosion of the soils undermining the foundation



Photo 6: Close-out of the erosion of the soils undermining the foundation