

Road No.	Bridge No.	FNDC Area	Roadway	Bridge Name	Span Arrangement	Description	Rough Order Cost Estimate	Aggregate Cost per year
2021-22								
2598	D42	North	Kaitaia-Awaroa Road	Kaitaia-Awaroa Road Bridge D42	4/9/9/9	Major Concrete Repairs/Pile Jacketing	\$165,000	
2598	D47	North	Kaitaia-Awaroa Road	Kaitaia-Awaroa Road Bridge D47	3/11/11/11	Major Concrete Repairs/Pile Jacketing	\$160,000	
1968	C03	North	Matai Bay Road	Matai Bay Road Bridge C03	2/9.2/9.2	Replacement of failing supports. Major repairs/replacement of bridge piles required. Abutments also showing issues.	\$220,000	
1759	F07	North	Hihi Road	Hihi Road Bridge F07	1/19.0	Replacement/repair of poor condition bridge deck	\$350,000	\$895,000
2022-23								
1721	M28	South	Grove Road	Grove Road Bridge M28	1/13.7	Replacement of deck and minor structural components	\$90,000	
1867	H20	North	Kohukohu Road	Kohukohu Road Bridge H20	3/11/14/11	Major Concrete Repairs/Pile Jacketing	\$175,000	
2454	UN23	North	Totara North Road	Totara North Road Culvert UN23	1/1.9	Major Concrete Repairs	\$175,000	
1844	E94	North	Kenana Road	Kenana Road Culvert E94	1/3.0	Concrete lining	\$150,000	
2420	T19	South	Te Karuwha Parade	Te Karuwha Parade Bridge T19	11/14.7	Corrosion and spalling noted. Significant chloride investigation required.	\$30,000	
1797	W31	South	Inksters Road	Inksters Road Bridge W31	1/6.0	Replacement of diaphragms, deck, minor structural components. Only 2 beams. Re-assessment of capacity required.	\$75,000	\$695,000
2023-24								
2315	E01	North	Silver Egg Road	Silver Egg Road Bridge E01	1/7.5	Replacement of the abutments	\$220,000	
1759	F06	North	Hihi Road	Hihi Road Bridge F06	1/19.3	Replacement/repair of poor condition deck	\$270,000	
1793	C11	North	Inland Road	Inland Road Bridge C11	1/12.2	Corrosion Reinstatement. Major Concrete Repairs.	\$110,000	
2096	E09	North	Oruru Road	Oruru Road Bridge E09	2/12.5/12.5	Major Concrete Repairs	\$110,000	
2420	T19	South	Te Karuwha Parade	Te Karuwha Parade Bridge T19	11/14.7	Major Concrete Repairs. Corrosion Reinstatement. Replacement of minor structural components	\$250,000	\$960,000
2024-25								
2444	I51	North	Tipa Tipa Road	Tipa Tipa Road Bridge I51	2/15.2/15.2	Upgrade of low strength bridge	\$220,000	
2208	B49	North	Puriri Place	Puriri Place Bridge B49	2/9.3/9.3	Upgrade of low strength bridge	\$220,000	
2484	R24	South	Waiare Road	Waiare Road Bridge R24	5/5.7/11.8/11.8/11.8/5.7	Replacement of Diaphragms. Steel Beam Repairs.	\$165,000	
1806	R01	South	Jennings Road	Jennings Road Bridge R01	1/8.0	Only 3 beams. Class I capacity in doubt.	\$165,000	
1785	L03	South	Horeke Road	Horeke Road Bridge L03	4/10.0	Major Concrete Repairs	\$165,000	
1979	I48	North	Matawherohia Road	Matawherohia Road Bridge I48	1/9.0	Abutments Replacement	\$175,000	\$935,000
2025-26								
2600	N15	South	Waimatenui / Mataraua Road	Waimatenui / Mataraua Road Bridge N15	6/12/12/12/12/12	Bridge Upgrade. Piers	\$275,000	
1867	H20	North	Kohukohu Road	Kohukohu Road Bridge H20	3/11/14/11	Major Concrete Repairs/Pile Jacketing	\$135,000	
1593	P04	South	Cherrington Road	Cherrington Road Bridge P04	1/9.0	Upgrade of low strength bridge	\$165,000	
1775	T06	South	Hupara Road	Hupara Road Bridge T06	1/6.0	Upgrade of low strength bridge	\$140,000	
2072	T41	South	Old Whangae Road	Kaitaia-Awaroa Road Bridge D47	1/13.0	Deck Replacement/Improvement. Corrosion Reinstatement.	\$85,000	
1867	H32	North	Kohukohu Road	Kohukohu Road Culvert H32	1/7.0	Major Concrete Repairs	\$110,000	
								\$910,000
2026-27								
2188	H08	North	Pukemiro Road	Pukemiro Road Bridge H08	4/6.2/12.0/12.0/6.2	Bridge Upgrade	\$275,000	
1739	M25	South	Harrison Road	Harrison Road Bridge M25	2/12.0/12.0	Upgrade of low strength bridge. Deck	\$165,000	
1684	E63	North	Fisher-Riley Road	Fisher-Riley Road Bridge E63	1/27.8	Bridge Upgrade	\$190,000	
1867	H32	North	Kohukohu Road	Kohukohu Road Culvert H32	1/7.0	Major Concrete Repairs	\$110,000	
2600	N16	South	Waimatenui / Mataraua Road	Waimatenui / Mataraua Road Bridge N16	4/12.0	Bridge Upgrade. Piers	\$165,000	\$905,000
2027-28								
1794	M08	South	Imms Road (Lake Omapere)	Imms Road (Lake Omapere) Bridge M08	1/12.0	Upgrade of low strength bridge	\$165,000	
1562	W60	South	Browns Road (Towai)	Browns Road (Towai) Bridge W60	1/10.0	Upgrade of low strength bridge	\$135,000	
2164	W04	South	Pipiwai Road	Pipiwai Road Bridge W04	1/11.0	Bridge Upgrade	\$165,000	
2164	W06	South	Pipiwai Road	Pipiwai Road Bridge W06	1/9.0	Bridge Upgrade	\$165,000	
2229	D61	North	Rangikohu Road	Rangikohu Road Bridge D61	3/9/9/9	Major Concrete Repairs/Pile Jacketing	\$110,000	
3174	T08	South	Waimangaro Road	Waimangaro Road Bridge T08	1/8.0	Only 3 beams. Class I capacity in doubt. Upgrade superstructure.	\$165,000	\$905,000
2028-29								
2345	N04	South	Stewards Road	Stewards Road Bridge N04	3/6.7/8.0/8.4	Only 3 beams. Class I capacity in doubt. Upgrade superstructure.	\$275,000	
2535	J14	South	Wekaweka Road	Wekaweka Road Bridge J14	3/3.3/3/3.3	Only 3 beams. Class I capacity in doubt. Upgrade superstructure.	\$220,000	
2100	P30	South	Otaenga Road	Otaenga Road Bridge P30	1/14.0	Upgrade of low strength bridge	\$165,000	
2543	G05	North	West Coast Road (Kohukohu)	West Coast Road (Kohukohu) Bridge G05	2/7.5/10.5	Pier Upgrade	\$110,000	\$770,000
2029-30								
3182	N03	South	Tawata Road	Tawata Road Bridge N03	1/12.4	Upgrade of low strength bridge	\$165,000	
3450	C09	North	Lake Ohia Flood bypass Rd	Lake Ohia Flood bypass Road Bridge C09	1/7.8	Upgrade of low strength bridge	\$110,000	
2114	T38	South	Owae Road	Owae Road Bridge T38	1/10.0	Upgrade of low strength bridge	\$165,000	
1627	W15	South	Davis Road	Davis Road Bridge W15	1/9.0	Upgrade of low strength bridge	\$165,000	
1627	W16	South	Davis Road	Davis Road Bridge W16	1/6.0	Upgrade of low strength bridge	\$165,000	\$770,000
2030+								
1867	H20	North	Kohukohu Road	Kohukohu Road Bridge H20	3/11/14/11	Pile Jacketing (remaining piles)	\$110,000	
2229	D61	North	Rangikohu Road	Rangikohu Road Bridge D61	3/9/9/9	Pile Jacketing (remaining piles)	\$110,000	\$220,000