

**Name:** Tanya Filia

**Subdivision:** South Hokianga



**Date:** 11/07/23

## Meetings Attended

Date	Meeting	Comments
7/6/23	KHCB meeting	Kaikohe In chambers
21//6/23	Combined community board workshop	Kaikohe In chambers
4/7/23	Executive KHCB meeting – finalise additions to strategic plan from previous work	FNDC conference space
5/7/23	KHCB meeting Followed by strategic planning hui	Kaikohe in chambers

## Community Issues

Issue name	Comment
Omanaia road slip – up to kura RFS 4157497 and others	<b>Temporary fix only</b> The kura staff and whanau need to ensure that the road is kept on the high priority list for a permanent fix.
Ninihi Road, Otatau RFS 4140344 RFS 4143310 RFS 4153319	Lodged RFS –Dust suppressant <b>Urgently needs addressing</b> Public forum – a roopu from Otatau attended our KHCB hui 15 March Voiced concern over their Kohanga Reo not being eligible for tar sealing due to it being run by Te Kohanga Reo Trust not ministry – <b>Disgraceful – this must be addressed NOW!!</b>
<u>Kokohuia road Omapere</u> <u>RFS numbers are</u> <u>March 2022/ 4096801 &amp;</u> <u>4102733</u> <u>Aug 2022 / 4122511</u> <u>RFS:3898749</u> <u>There are others</u>	<u>Historical RFS put through from many Kokohuia Road residents. I have noted some of these RFS numbers.</u> Turning more into a wide track than a road  <b><u>An elected member/ NTA site hui with be appropriate to see first-hand the state of this road.</u></b>
Fire Hydrants Omapere/Opononi RFS: 4135612 Date: 21.11.22	FNDC personnel TM – met with Omapere Brigade senior fire fighter, and representative from Ventia on Wednesday 21 June to complete site visits to Opononi fire hydrants – the purpose was to go through the difficult hydrants and carry out maintenance. This was achieved. Thanks to all those concerned  FNDC worker will request GIS team to provide updated maps for the fire brigade as part of this exercise. <b>Update</b> – FNDC GIS specialist advised Brigade that all the fire hydrant mapping information is provided directly to the FENZ Wellington headquarters – the information is then provided to fire brigades via their internal smart maps system. Individual brigades will need to access this themselves.

<p>RFS 4093246</p> <p>RFS 4161249 – 4WD vehicles on verges -</p>		<p>Footpaths and Berms Opononi – on SH12 Opononi in front of the BOWLING CLUB</p> <p>More damage done and a recent RFS sent in by me in regards to the state of the footpaths <b>still !!!</b>– clean up needed – maintenance needed to clean gravel travel and debris from Fairlie Crescent intersection to bowling club.</p> <p>This has not been remedied.</p>
<p>RFS 4166146</p> <p>Corner Omanaia Road/ Statehighway 12 Oue end</p>	 <p>clay mud and debris from what I can only assume, is what maintenance contractors, have cleared from slips and have dumped into this space, a layby area. Students catch buses from this junction, whanau park here to drop off and pick up. It needs to be removed, in what world is this acceptable practice? it is beginning to flood/pool with water and looks dreadful. This has been referred to Waka Kotahi.</p>	
<p>RFS 4166045</p>	<p>Statehighway 12 Pakanae access road to Opononi RFS raised. Road partially cleared for access more clearing to be done. Steve McNally followed this matter up.</p>	
<p>RFS 4165589</p>	<p>The Opononi hall renovations have been undertaken, however the hall committee have raised concerns about a number of items and Council staff will be meeting with them to discuss. A plan will be outlined for the outstanding work.</p>	

**Requests for Service (RFS) – see above the RFS recorded against the commentary column.**