
Date: 30 June 2020

Subject: Freese Park, Omapere – Erosion issues

Background

Since the photo taken in December 2018, the Freese Park foreshore has continued to deteriorate rapidly.

This coastal erosion has affected several Council assets including a picnic table, rubbish bin and what appeared to be old pipe work etc.

However, the speed of this deterioration is now putting not only putting council assets at risk e.g.: playground and public toilet facilities but also neighbouring property asset's e.g.: fencing.

Photo images below capture the rate of coastal erosion affecting the Freese Park foreshore area since December 2018:



December 2018



December 2019

The following photo collage was taken 23 June 2020:





It is believed that works carried out to the west of Freese Park a few years ago has only escalated and channeled the damage being done along this foreshore area.